

NPWT Irreparable Air Leak / Device Failure: Alternate Dressing - Cut & Cover

(Click on the title to access the video)

This 1:50-minute video demonstrates how to manage a Negative Pressure Wound Therapy (NPWT) dressing in the event of an irreparable leak or machine/device failure by cutting the tubing and covering with a dressing. Please note; the video may take 1-2 minutes to download.